

U.S ENVIRONMENTAL PROTECTION AGENCY, REGION II

POLLUTION REPORT

211284



DATE: April 29, 1988

Region II
Response and Prevention Branch
Edison, N.J. 08837
(201) 548-8730 - Commercial & FTS
24 Hour Emergency

TO: C. Daggett, EPA
S. Luftig, EPA
R. Salkie, EPA
F. Rubel, EPA
G. Zachos, EPA
B. Sprague, EPA
ERD, Washington, DC
(E-MAIL)
J. Marshall, EPA
D. Karlen, EPA
F. Frisco, EPA
J. Czapor, EPA
J. Trela, NJDEP
TAT

POLREP NO: Twenty eight (28)
INCIDENT NAME: Ringwood Mines
SITE NO: 62
POLLUTANT: Lead Paint Sludges
CLASSIFICATION: Major
SOURCE: Ford International Services, Inc.
LOCATION: Ringwood, Passaic County, New Jersey
AMOUNT: Approximately 7500 tons
WATER BODY: Groundwater

1. SITUATION:

A. Paint sludges from the automotive industry were disposed of in a large mine area in Ringwood, Passaic County, New Jersey.

B. Based upon the concentration of lead in the EP Toxicity leachates, the paint sludge exhibits the characteristics of a hazardous waste as promulgated in 40 CFR, 261, Subpart C (USEPA hazardous waste number D008).

C. A consent order was signed by Ford International Services, Inc. accepting responsibility for the total site clean-up.

D. Four areas containing solidified paint sludge have been designated as pits A, B, C and D. Pits A, B, and D are located on-site and are being excavated first. Pit C, located at an isolated area off site, will be addressed last.

2. ACTION TAKEN:

A. A stagnant pool of groundwater has accumulated in pit A.

B. Backfilling of areas A and C awaits laboratory confirmation on the second set of soil samples taken.

C. Backfilling has been completed in areas D and B.

D. No shipments of dirt were made.

E. EPA continues to monitor PRP activities.

3. FUTURE PLANS AND RECOMMENDATIONS:

A. Pending the analytical results from soil samples taken from each area.

Final Polrep _____ Further
Polreps
Forthcoming _____ Submitted by _____
Lise Perderson, OSC
Response and
Prevention Branch

Date Released _____